ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: M04259
Date Received: 06/18/09
Date Extracted: 06/19/09
Date Analyzed: 06/23/09
Matrix: Water
Units: ug/L (ppb)

Client: Project: Lab ID: Data File: Alaskan Copper Works

Metro Self Monitor, PO M04259 906177-01

Data File: 906177-01.029
Instrument: ICPMS1
Operator: AP

Operator:

Internal Standard: Germanium % Recovery: 92

Lower Limit: 60 Upper Limit: 125

Analyte: Concentration ug/L (ppb)

 Chromium
 488

 Nickel
 573

 Copper
 663

 Zinc
 31.1

ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: Date Received: Method Blank

Client: Project: Alaskan Copper Works

Date Extracted:

Not Applicable 06/19/09 06/19/09

Project: Lab ID: Metro Self Monitor, PO M04259 I9-253 mb

Date Analyzed: Matrix:

Units:

06/19/09 Water ug/L (ppb) Data File: Instrument: 19-253 mb.042

Operator:

ICPMS1 AP

Internal Standard:

% Recovery:

Lower Limit: 60 Upper Limit: 125

Germanium

Concentration

<1

<1

<1

<2

Analyte: Concentration ug/L (ppb)

Chromium
Nickel
Copper
Zinc

ENVIRONMENTAL CHEMISTS

Date of Report: 06/25/09 Date Received: 06/18/09

Project: Metro Self Monitor, PO M04259, F&BI 906177

QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 906151-01 (Duplicate)

				Relative		
Analyte	Reporting Units	Sample Result	Duplicate Result	Percent Difference	Acceptance Criteria	
Chromium	ug/L (ppb)	5.63	5.57	10 ST 11 SV	0-20	
Nickel	ug/L (ppb)	21.6	22.5	4	0-20	
Copper	ug/L (ppb)	88.6	89.8	1	0-20	
Zinc	ug/L (ppb)	35.1	35.4	1	0-20	

Laboratory Code: 906151-01 (Matrix Spike)

				Percent	
		Spike	Sample	Recovery	Acceptance
Analyte	Reporting Units	Level	Result	MS	Criteria
Chromium	ug/L (ppb)	20	5.63	76 b	50-150
Nickel	ug/L (ppb)	20	21.6	7 6 b	50-150
Copper	ug/L (ppb)	20	88.6	81 b	50-150
Zinc	ug/L (ppb)	50	35.1	69 b	50-150

Laboratory Code: Laboratory Control Sample

Analyte	Reporting Units	Spike Level	Percent Recovery LCS	Acceptance Criteria		
Chromium	ug/L (ppb)	20	94	70-130		
Nickel	ug/L (ppb)	20	90	70-130		
Copper	ug/L (ppb)	20	92	70-130		
Zinc	ug/L (ppb)	50	89	70-130		

ENVIRONMENTAL CHEMISTS

Data Qualifiers & Definitions

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probability.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb The analyte indicated was found in the method blank. The result should be considered an estimate.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht The sample was extracted outside of holding time. Results should be considered estimates.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- \underline{nm} The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve The value reported exceeded the calibration range established for the analyte. The reported concentration should be considered an estimate.
- vo The value reported fell outside the control limits established for this analyte.
- x The pattern of peaks present is not indicative of diesel.
- y The pattern of peaks present is not indicative of motor oil.

Send Report To Season	Thomps) 1		SAMPLERS (SI	gnature)		_	- "			B. *		Fage # TURNA	COUND TIME
Company ALASKAN Coppen Works Address 628 Harrand ST				PROJECT NAMENO. PO# Medio Seld monder Moyz				1.00	RUS	H <u> </u>	1 (2 Weeks)			
City, State, ZIP South	le us	5813		REMARKS							57.6. 14.6.	□ Retu □ Will	ose after m sample	
				 					ANA	LYS	ES REQI	UESTED		
Sample ID	Lab ID	Date	Time	Sample Type	# of containers	TPH-Diesel	TPH-Gasoline	VOCs by 8260	SVOCs by 8270	HFS	A CUME 2		9	Notes
mo4259	01	91805	12:45	HZO	2			1			7			

				╅╼╊╼╼	
Friedman & Bruya, Inc.	J SIGNATURE	PRINT NAME	COMPANY	DATE	TIME
3012 16th Avenue West	Relinquicked by 1	> (-xexelc Tloopse	ACW	9/8/09	2:16P
Seattle, WA 98119-2029	Received by: M aw aw	- Whan Phan	FeBT	6/18/09	2:16
Ph. (206) 285-8282	Relinquished by:	- Andrew			
Fax (206) 283-5044	Received by:				
FORMS\COC\COC.DOC	= = = = = = = = = = = = = = = = = = = =	<u></u>	Samples rece	ived at 25	_ .°C

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

June 25, 2009

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on June 18, 2009 from the Metro Self Monitor, PO M04259, F&BI 906177 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU0625R.DOC